

Report Summary – 2003

Project for maintenance of a forest

Regarding a project for maintenance of a forest, the spray of concrete failed to meet the purpose of this construction because the spray was greatly different from the design. For example, there was a deficiency in the thickness of the sprayed concrete for the protection of a slope, and concrete was not closely adhered to the ground.

(1 case; 7.26 million yen)